

4-VOLT VALVES

COSSOR	MARCONI-OSRAM	MULLARD	MAZDA	SIX-SIXTY
410 S.G.	S.410	P.M.14	—	4075 S.G.
410 R.C.	H.410	P.M.3A.	—	4075 R.C.
410 H.F.	H.L.410	P.M.3	—	4075 H.F.
410 L.F.	L.410	P.M.4.D.X.	—	410 D.
410 P.	P.410	P.M.4	—	410 P.
425 X.P.,	P.415,	P.M.254	P.425	420 S.P.
415 X.P.	P.425			

6-VOLT VALVES

610 S.G.	S.610	P.M.16	—	6075 S.G.
610 H.F.	H.L.610	P.M.5X.	H.L.610	6075 H.F.
610 L.F.	L.610	P.M.6D.	—	610 D.
610 P.	P.610	P.M.6	—	610 P.
625 P.	P.625	P.M.256	P.625B.	625 S.P.
610 X.P.	P.625A.	P.M.256A.	P.625A.	625 S.P.A.
615 P.T.	P.T.625	P.M.26	—	617 P.P.

INDIRECTLY HEATED A.C. MAINS VALVES

—	—	V.P.4	—	H.P.2AC.
M.S.Pen.	—	S.P.4	—	H.P.1AC.
MVSG.	VMS.4	M.M.4V.	AC/SG.VM.	4MMAC.
—	—	S.4.V.A.	AC/S2	4X. SG.AC.
MSG/LA.	M.S.4	S.4.V.B.	AC/SG.	4Y.SG. AC.
—	MS/4/B } MHD.4	T.D.D.4	—	—
—	—	S.D.4	—	—
4I MH.	—	904V.	AC2/HL.	4DX.AC.
4I MHF.	MH 4	354V.	AC.HL.	4GPAC.
4I MHL.	MHL.4	244V.	—	4HLAC.
4I MLF.	—	164V.	—	4LAC.
4I MP.	ML.4	104V.	AC.P	4PAC.
MP.Pen.	—	PEN.4V.	—	4Pen. A.C.
MP.Pen. A.	M.P.T4	PEN.4VA.	AC.Pen.	—